## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. DATED

: 6,734,065 B2

: May 11, 2004

INVENTOR(S) : Yim et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 7,

Line 42, "electrode 231 crossing" should read -- electrode 23l crossing --.

Column 10,

Line 25, "than equivalent oxide" should read -- than an equivalent oxide --.

Column 11,

Line 3, "than equivalent oxide" should read -- than an equivalent oxide --.

Signed and Sealed this

Seventh Day of December, 2004

JON W. DUDAS Director of the United States Patent and Trademark Office